



458116

KATY ROWE

DETROIT

G/K

POTENTIAL GROUND WATER CONTAMINATION SOURCEIDENTIFICATION AND PRELIMINARY ASSESSMENT

This form is completed for each potential hazardous waste site to help set priorities for site inspections. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections. If information is not available, place an "x" in the space provided.

SITE IDENTIFICATION

COMPANY NAME SANFILL LANDFILL # 2 (SEE NOTE ON OTHER SIDE)

ADDRESS ~~1911~~ HAMLIN RD N.W. CORNER OF DEQUINDRE & HAMLIN RD

LOCATION (COUNTY, TOWN & RANGE) OAKLAND CO. AVON TWP 10 ACRES

OWNER/OPERATOR JOHN SPOKAESKI - OPERATOR ; OWNER: MARION L. PIHAJLIC

HOW LONG HAS THIS FACILITY BEEN OPERATING AT THIS SITE? REPORTED 1968 TO 1974

HAS THERE EVER BEEN AN OWNERSHIP TRANSFER? YES

IF SO WHEN? 1971 FROM AR ; 1975 ; 1976 ← JOHN SPOKAESKI TO MARION L. PIHAJLIC

PREVIOUS OWNER? ARTHUR HILL TO M.A.L. ENTERPRISES ; M.A.L. TO JOHN SPOKAESKI OF SANFILL, INC.

OPERATION CHARACTERIZATION

TYPE OF OPERATION (I.E. MANUFACTURING, LANDFILL, ETC.) LANDFILL

WASTE CHARACTERIZATION

Waste type:

☒ Unknown ☒ Liquid ☒ Solid ☐ Sludge ☐ Gas

Waste characteristics:

☒ Unknown ☐ Corrosive ☐ Ignitable ☐ Radioactive ☐ Highly Volatile

☐ Toxic ☐ Reactive ☐ Inert ☐ Flamable

☐ Other Specify \_\_\_\_\_

Waste description (metal sludges, PCB's, etc.) REPORTEDLY OCCIDENTAL

PETROLEUM ADMITTED TO U.S. CONGRESSIONAL SUBCOMMITTEE THAT THEY DUMPED 700 TONS OF HALOGENATED ALIPHATICS BETWEEN 1965 ; 1970. (SOURCE: KATY KIRWIN, ROCHESTER ECCENTRIC)

PROBLEM CHARACTERIZATION (I.E. UNLINED SEEPAGE LAGOON, IMPROPER BARREL DISPOSAL, ETC. FIVE FEET OF COMPACTED CLAY WERE TO HAVE BEEN PLACED ABOVE WATER TABLE ELEVATION AS A LINER. INSPECTION OF 10-2-72 QUESTIONED WHETHER THIS WAS BEING DONE. ALSO, REQUIRED CLAY DIKES TO PROTECT SURFACE STREAM WERE NOT PLACED.

LIST ALL APPLICABLE PERMITS HELD BY THE SITE (FILL IN DATE OF ISSUANCE & PERMIT  
NUMBER) BOND: INTERNATIONAL FIDELITY INSURANCE CO., NEW JERSEY  
# CP 779 8-30-76

NPDES \_\_\_\_\_  
Air \_\_\_\_\_  
Solid waste ACT 87, P.A. 1965 SANDHILL #2  
LIC # 4275 1-13-77  
Inland lakes \_\_\_\_\_  
Liquid industrial waste \_\_\_\_\_  
Groundwater discharge \_\_\_\_\_  
Soil & sedimentation \_\_\_\_\_  
Other (specify) \_\_\_\_\_

COMPLIANCE HISTORY FAILURE TO CONSTRUCT LANDFILL AS REQUIRED,  
INADEQUATE COVER

## CONTAMINATION INFORMATION

HAS THERE BEEN ANY ATTEMPT TO MONITOR THE GROUNDWATER IN THE PAST *No*

If so, give the location or identification number of the wells  $x$ .

List any pertinent monitoring data (include date and laboratory used for analysis) SITE IS ABOUT 1200 FT EAST OF STAN'S TRUCKING LANDFILL, A KNOWN SOURCE OF WATER POLLUTION. ADDITIONAL CONTAMINATION FROM THIS SITE MAY BE HARD TO PROVE.

GIVE THE LOCATION & DISTANCE TO THE NEAREST PRIVATE WELL 800 FT TO S.W.

GIVE THE SOURCE OF MUNICIPAL WATER SUPPLY      x

LIST ANY KNOWN GEOLOGICAL CHARACTERISTICS OF THE AREA GENERALLY, ABOUT  
30 FT SAND (WET AT 10 FT) THEN 20+ FT CLAY

DEPARTMENT ACTIONHISTORY OF SITE INSPECTIONS (LIST DATE, INSPECTING AGENCY & RESULTS) BLOWING PAPERS1<sup>ST</sup> INSPECTION 11-30-71 BY OAKLAND CO. H.D. ; 6-9-72 INSPECTION BY OCHDASKING FOR PLANS FOR ADDITIONAL 4 ACRES, SITE APPROVED ; 10-2-72 DNRINSPECTION NOT APPROVED - INADEQUATE COVER, REFUSE PLACED INTO LADD DRAIN  
CLAY LAYER ; DIKES NOT INSTALLED. INSPECTION BY O.C.H.D. 10-24-73 INDICATES SITE  
WAS COMPLETED.

REGULATORY ACTIONS (NOTICES OF NONCOMPLIANCE &amp; VIOLATIONS, DATES &amp; REASONS)

6-16-75 O.C.H.D. SITE NEEDS 2' FINAL COVER ; SEEDING

REMEDIAL ACTIONS REQUESTED (ACTIONS &amp; DATES)

Were these actions accomplished? NOT KNOWN

ORIGINAL OWNER WAS ARTHUR HILL. SITE OPERATED BY J. FONS. CO.  
10/68 TO EARLY 1971. NEW OWNER, M.A.L. ENTERPRISES, STARTED  
OPERATING 7-6-71 AND STOPPED DURING 1974. IN 1975 OWNERSHIP  
CHANGED TO JOHN SPOKAESKI OF SANDFILL, INC. AND WAS LICENSED  
FOR MAINTENANCE OF A COMPLETED LANDFILL. 1976 OWNERSHIP BY M.L. PIHAJIC  
THE NEAREST SURFACE WATER (LADD DRAIN) IS ABOUT 100 FT, NORTH.

NO  
DUMPING  
BY  
FONS  
CO.

Case name SANDFILL #2PRELIMINARY PROBLEM ASSESSMENTDate 12-18-79

## POTENTIAL HAZARDS (CHECK ALL APPLICABLE CATEGORIES)

Human health	_____	Noticeable odors	_____
Contamination of water supply	<u>✓</u>	Contamination of soils	_____
Contamination of groundwater	<u>✓</u>	Property damage	_____
		Sewer/storm drain problems	_____
Contamination of surface water	<u>✓</u>	Erosion problems	_____
Contamination of food chain	_____	Inadequate security	_____
Damage to flora/fauna	_____	Other (specify)	_____
Fish kill	_____		_____
Contamination of air	_____		_____
Fire or explosion	_____		_____
Spills/leaking containers (runoff) standing liquids	_____		
Incompatible wastes	_____		
Midnight dumping	<u>MM</u>		

WHAT ADDITIONAL INFORMATION IS REQUIRED? BACKGROUND WATER QUALITYDESCRIBE ANY NECESSARY ACTIONS WHICH SHOULD BE UNDERTAKEN? (ADDITIONAL SAMPLING, SITE INSPECTION, ETC.) MONITOR WELLS, SITE INSPECTION

SUMMARY OF ACTIONABLE VIOLATIONS

Case Name SANDFILL #2

The following is a list of violations which may provide a basis for the development of enforcement strategy. The violations fall into two basic categories: 1. Operation without a permit or 2. violation of a permit, final order, consent agreement etc. Please note any of these violations during the course of your review.

Violation of Act 245, P.A. 1929, the  
Water Resources Commission Act  
(discharge violation)

x

No permit \_\_\_\_\_

Violation of permit \_\_\_\_\_

Surface water discharge \_\_\_\_\_

Groundwater discharge \_\_\_\_\_

Violation of Part 5 Rules for  
Act 245, P.A. 1929

x

Illegal storage \_\_\_\_\_

Improper storage \_\_\_\_\_

No PIPP \_\_\_\_\_

PIPP not implemented correctly \_\_\_\_\_

Violation of Act 641, P.A. 1978, the  
Solid Waste Management Act

No license \_\_\_\_\_

Violation of license \_\_\_\_\_

Other violations (failure to report critical materials, improper disposal of PCB's,  
illegal waste removal, etc.) POSSIBLE HAZARDOUS WASTE DUMP

designed plan was not followed.